## CITY OF SPRINGFIELD INTER-OFFICE MEMORANDUM

BOB - STOVE

DEPARTMENT	
	SOURCE ODOR A HUY MY
<	Scenie - 4161 S. Seenie -
	R.J. REYNOLDS OFFICE IN
	THAT STRIP CENTER). MAY BE ODOR FROM JAMES R.
	FORTE MAIN ENTERING
	FAULTY PLUMBING. PROBABLY WOULD REQUIRE SMOKE TEST.
	CHECK ONT A.S.A.P.
	SIGNED Landy
	4161 5. Scenic

## CITY OF SPRINGFIELD INTER-OFFICE MEMORANDUM

ATTENTION OF FILE

cc: file

DATE July 25, 1989

Steve Short

4161 S. Scenic

DEPARTMENT		
	An investigation was performed at 4161 South Scenic in response to a complaint received by Randy Lyman on this date. I talked to Ann Marrie Skaff, an office worker at the above address, who indicated she and others working in the R.J. Reynolds office had smelled a foul odor in their suite. She stated she could smell it the first thing in the morning and after returning from lunch but did not after being in the building for a period of time. She also noted people entering the building observed a foul smell. She also stated she had gone home with headaches after working in the office. My investigation revealed the floor drain in one of the restrooms had water added that day, which may indicate it had been dry because I couldn't smell a specific odor. I checked for H2S and explosive atmosphere and could not detect either. I also checked two other suites, the former Baby Ducks, and 4183 South Scenic I agree with Randy that this complex should be smoke tested as there is a potential H2S and carbon monoxide source with the James River Lift force main terminating at or near where the complex connected.	

SIGNED\_\_\_\_